




Ground level Police entrance:
Water damage, rotted sheet rock and
mold.



Ground floor – Police:
Ground box for electrical exposed.



Ground level Police Cell area:
Main water line leaking and
rusting away.



Ground level Police Vault area:
Mold and water damage